



6312 West Oakton Street  
Morton Grove, IL 60053-2723  
847-965-1999  
Fax 847-965-1991

June 15, 2018

PBS Engineering and Environmental  
Dale Voeller  
4412 SW Corbett Avenue  
Portland, OR 97239  
USA


### Alpha Track Radon Test Results

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
360135	3.5 ± 3%	Room 243-D	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/11/2018	
360137	2.0 ± 4%	Weight Room	North HS 1001 SE 135th Ave Portland, OR 97233	12/5/2017	6/7/2018	
360139	2.9 ± 4%	Room 233C-c	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
360140	3.1 ± 3%	Cafeteria	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
360141	3.3 ± 3%	Room 245A	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/11/2018	
360142	1.5 ± 5%	Cardio Room	North HS 1001 SE 135th Ave Portland, OR 97233	12/5/2017	6/7/2018	
360145	15.0 ± 2%	Speech Room	North Powellhurst E.S. 1400 SE 135th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
360150	0.1 ± 13%	BLANK	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
361351	2.8 ± 4%	Room 234	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
361354	10.9 ± 2%	Boys Locker Room Office	North HS 1001 SE 135th Ave Portland, OR 97233	2/15/2018	6/7/2018	
361355	16.6 ± 2%	Boys Locker Room Team Office	North HS 1001 SE 135th Ave Portland, OR 97233	2/15/2018	6/7/2018	
361357	3.5 ± 4%	Girls Locker Room Office	North HS 1001 SE 135th Ave Portland, OR 97233	2/15/2018	6/7/2018	
361361	7.9 ± 3%	Room 226 (Woodshop) Office	South HS 1500 SE 130th Avenue Portland, OR 97233	2/15/2018	6/7/2018	
361362	0.1 ± 15%	BLANK	North HS 1001 SE 135th Ave Portland, OR 97233	2/15/2018	6/7/2018	

Analyzed By:  06/14/ 2018  
 \_\_\_\_\_  
 Jeremy Kieser  
 Radon Analyst  
 Analysis Date

\*\*\*END REPORT\*\*\*

\* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.


Report shall not be reproduced except in its entirety without the approval of RSSI.

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
360132	2.9 ± 3%	Staff work room	West Union Elementary School 23870 NW West Union Rd Hillsboro, OR 97124	11/13/2017	5/30/2018	
360134	3.0 ± 3%	Staff work room-duplicate	West Union Elementary School 23870 NW West Union Rd Hillsboro, OR 97124	11/13/2017	5/30/2018	
360136	2.5 ± 4%	Room 233C-a	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
360143	3.1 ± 3%	Room 171	North HS Annex 1001 SE 135th Ave Portland, OR 97233	12/5/2017	6/7/2018	
360144	1.6 ± 5%	Horticulture Bldg. - Rm. 275	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
361352	2.8 ± 4%	Room 234-Duplicate	South HS 1500 SE 130th Avenue Portland, OR 97233	12/5/2017	6/7/2018	
361353	2.9 ± 4%	Costume Shop	South HS - PAC 1500 SE 130th Avenue Portland, OR 97233	2/15/2018	6/7/2018	
361356	16.3 ± 2%	Boys Locker Room Team Office (Dup.)	North HS 1001 SE 135th Ave Portland, OR 97233	2/15/2018	6/7/2018	
361358	5.6 ± 3%	Girls Locker Room Office	South HS 1500 SE 130th Avenue Portland, OR 97233	2/15/2018	6/7/2018	
361359	6.4 ± 3%	Boys Locker Room wrestling Office	South HS 1500 SE 130th Avenue Portland, OR 97233	2/15/2018	6/7/2018	
361360	5.3 ± 3%	Boys Locker Room Office	South HS 1500 SE 130th Avenue Portland, OR 97233	2/15/2018	6/7/2018	
361368	2.6 ± 5%	Gym Building - Room 36	Gilbert Heights ES 12839 SE Holgate Blvd Portland, OR 97236	3/16/2018	6/7/2018	

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
361371	2.5 ± 6%	Maintenance Shop	South Powellhurst 2900 SE 122nd Avenue Portland, OR 97236	4/12/2018	6/7/2018	
361373	0.8 ± 10%	Bus Garage Break (Storage) Room	South Powellhurst 2900 SE 122nd Avenue Portland, OR 97236	4/12/2018	6/7/2018	

Analyzed By:  06/15/ 2018

---

Jeremy Kieser  
Radon Analyst

Analysis Date

\*\*\*END REPORT\*\*\*

\* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.