



6312 West Oakton Street
Morton Grove, IL 60053-2723
847-965-1999
Fax 847-965-1991

May 07, 2019

PBS Engineering & Environmental
Dale Voeller
4412 SW Corbett Avenue
Portland, OR 97239
USA

Alpha Track Radon Test Results

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
345602	3.4 ± 4%	Counseling Office, South Wall above Desk	Ventura Park Elementary School 145 SE 117th Avenue Portland, OR 97216	12/7/2018	5/2/2019	
345603	4.2 ± 4%	Multi-Purpose room 2, North Wall	Ventura Park Elementary School 145 SE 117th Avenue Portland, OR 97216	12/7/2018	5/2/2019	
345606	5.2 ± 3%	Principals Office, West Wall	Ventura Park Elementary School 145 SE 117th Avenue Portland, OR 97216	12/7/2018	5/2/2019	
345609	3.1 ± 4%	Faculty Lunch Room, South Wall by fridge	Ventura Park Elementary School 145 SE 117th Avenue Portland, OR 97216	12/7/2018	5/2/2019	
345612	4.0 ± 4%	Multi-Purpose room 1, SE wall	Ventura Park Elementary School 145 SE 117th Avenue Portland, OR 97216	12/7/2018	5/2/2019	
345614	4.3 ± 4%	Main Office, North Wall	Ventura Park Elementary School 145 SE 117th Avenue Portland, OR 97216	12/7/2018	5/2/2019	

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
-----------------	-------	---------------	--------------	------------	----------	-------

Analyzed By:	<i>Aaron J. Morris</i>	05/07/ 2019
	Aaron Morris Radon Analyst	Analysis Date

*****END REPORT*****

* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.

Customer Number: 0923

Page 2 of 2