
September 17, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

MILL PARK ES

MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9014902	140 - STAGE OFFICE	2018-09-10 @ 7:00 pm	2018-09-14 @ 6:00 am	3.3 ± 0.5	2018-09-17
9014909	147 - SUN OFFICE	2018-09-10 @ 7:00 pm	2018-09-14 @ 6:00 am	2.6 ± 0.4	2018-09-17
9014910	151 - OFFICE	2018-09-10 @ 7:00 pm	2018-09-14 @ 6:00 am	1.1 ± 0.3	2018-09-17
9014907	CAFETERIA - EAST	2018-09-10 @ 7:00 pm	2018-09-14 @ 6:00 am	2.1 ± 0.4	2018-09-17
9014908	CAFETERIA - WEST	2018-09-10 @ 7:00 pm	2018-09-14 @ 6:00 am	1.9 ± 0.4	2018-09-17
9014905	STAGE	2018-09-10 @ 7:00 pm	2018-09-14 @ 6:00 am	2.0 ± 0.4	2018-09-17

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498