



6312 West Oakton Street  
 Morton Grove, IL 60053-2723  
 847-965-1999  
 Fax 847-965-1991

May 07, 2019

PBS Engineering & Environmental  
 Dale Voeller  
 4412 SW Corbett Avenue  
 Portland, OR 97239  
 USA

**Alpha Track Radon Test Results**

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
345618	10.1 ± 2%	Room 6, West Wall	Gilbert Park Elementary School 13132 SE Ramona Street Portland, OR 97236	12/7/2018	5/2/2019	

Analyzed By: Aaron J. Morris      05/07/ 2019  
 Aaron Morris      Analysis Date  
 Radon Analyst

**\*\*\*END REPORT\*\*\***

\* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.