



6312 West Oakton Street
 Morton Grove, IL 60053-2723
 847-965-1999
 Fax 847-965-1991

May 07, 2019

PBS Engineering & Environmental
 Dale Voeller
 4412 SW Corbett Avenue
 Portland, OR 97239
 USA

Alpha Track Radon Test Results

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
361365	6.1 ± 3%	Main Conference, North Pole	MCEP Glisan 12405 NE Gilsan Street Portland, OR 97230	12/7/2018	5/2/2019	
361370	6.2 ± 3%	Main Conference, South Pole	MCEP Glisan 12405 NE Gilsan Street Portland, OR 97230	12/7/2018	5/2/2019	

Analyzed By: Aaron J. Morris 05/07/2019
 Aaron Morris Analysis Date
 Radon Analyst

END REPORT

* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.