



6312 West Oakton Street  
Morton Grove, IL 60053-2723  
847-965-1999  
Fax 847-965-1991

May 07, 2019

PBS Engineering & Environmental  
Dale Voeller  
4412 SW Corbett Avenue  
Portland, OR 97239  
USA

### Alpha Track Radon Test Results

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
361367	4.4 ± 3%	Gym Office, West Wall	Menlo Park Elementary School 12900 NE Gilsan Street Portland, OR 97230	12/7/2018	5/2/2019	
361374	9.5 ± 2%	Quiet Room, SE Wall	Menlo Park Elementary School 12900 NE Gilsan Street Portland, OR 97230	12/7/2018	5/2/2019	

Analyzed By:

Aaron Morris  
Radon Analyst

05/07/ 2019

Analysis Date

\*\*\*END REPORT\*\*\*

\* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.