



6312 West Oakton Street
Morton Grove, IL 60053-2723
847-965-1999
Fax 847-965-1991

May 09, 2019

PBS Engineering & Environmental
Dale Voeller
4412 SW Corbett Avenue
Portland, OR 97239
USA

Alpha Track Radon Test Results

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
345551	6.6 ± 3%	Room 134, Far Wall	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	12/21/2018	5/2/2019	
345552	6.4 ± 3%	Boys Locker office, East Wall	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	12/21/2018	5/2/2019	
345557	5.6 ± 3%	Girls Locker office, East Wall	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	12/21/2018	5/2/2019	
345615	5.4 ± 3%	Gym 2, East Wall	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	12/21/2018	5/2/2019	
345620	3.7 ± 4%	Custodian's Office	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	1/17/2019	5/2/2019	
361369	6.1 ± 3%	Room 148, North Wall	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	12/21/2018	5/2/2019	

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
-----------------	-------	---------------	--------------	------------	----------	-------

Analyzed By:

Aaron J. Morris

05/07/ 2019

Aaron Morris
Radon Analyst

Analysis Date

*****END REPORT*****

* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes


Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.

Customer Number: 0923

Page 2 of 3

Detector Number	pCi/L	Test Location	Test Address	Start Date	End Date	Note*
361375	4.9 ± 3%	Room 186	Ron Russell Middle School 3955 SE 112th Avenue Portland, OR 97266	12/21/2018	5/6/2019	

Analyzed By:  05/09/ 2019

Elektra Musich
Radon Analyst

Analysis Date

END REPORT

* 1-Broken Seal, 2-Damaged Filter, 3-Loose Test Material, 4-Missing Test Material, 5-Missing End Date, 6-Missing Start Date, 7-Less Than 8 Days, 8-Past Expiration Date, 9-Missing Both Dates, NA-No applicable notes

Analytical results showing the radon concentration relate only to the device(s) tested in the condition as received by RSSI. Results were calculated based on information provided by the client.

Report shall not be reproduced except in its entirety without the approval of RSSI.